



9-10-64

SERVICE PARTS LIST

THE AUSTIN-HEALEY SPRITE

Item No.	DESCRIPTION	Commencing (C) 501		Qty. per Veh.	MODIFICATIONS		REMARKS
		Part Number	Illus. No.		New Part Number	Change Point	
	<b>TACHOMETER AND FITTINGS (Optional Extra)</b>						
1	Tachometer		2A9068	1			
2	Bezel		N.S.P.	1			Was 27H307
3	Slip—ring		N.S.P.	2			Was 27H406
4	Strap—fixing		AJH5176	3			Part No. change. Was 27H429
5	Ring (rubber)		AJH5178	4			
6	Glass		N.S.P.	5			Was AJH5177
7	Screw		17H1544	6			
8	Nut		17H1804	7			
9	Washer for screw		17H1841	8			
10	Bulb holder and cable		2A9007	9			
11	Bulb		BFS987	10			Part No. change. Was 2H4782
12	Cable—tachometer		2A9104	1	BHA4086		
13	Cable (outer)	RHD	17H1497	11	17H1679	] Com. (C) 3444	
14	Cable (inner)		17H1499	12	17H1678		
15	Cable—tachometer		2A9106	1			
16	Cable (outer)	LHD	17H1498	1			
17	Cable (inner)		17H1344	1			
18	Ratio box—cable to dynamo		2A9105	13	13H632		
19	Grommet—cable through dash		RFN805	1			
20	Bracket for cable		1K1977	14			
21	Grommet—cable through bracket	RHD	8H822	15			
	<b>TONNEAU COVER (Optional Extra)</b>						
22	Tonneau cover assembly (Black)	RHD	AHA5256	16			
23	Tonneau cover assembly (Black)	LHD	AHA5207	1			
24	Tonneau cover assembly (White)	RHD		1	AHA5482	] Com. (C) 13543	
25	Tonneau cover assembly (White)	LHD		1	AHA5483		
26	Fastener—top portion		14B2405	4			
27	Eyelet		14A6507	2			Part No. change. Was 97H498
28	Washer for eyelet		14A6508	2			Part No. change. Was 97H497
29	Fastener		2H5008	3			Part No. change. Was 7H9961
30	Fastener—zip (Black)		AHA5657	1			
31	Fastener—zip (White)			1	AHA5658	Com. (C) 18543	
32	Stud		97H717	3			
33	Nut		AJD8012Z	3			
34	Washer (leather)		2K4936	4			